# Oil Field Environmental Incident Summary

**Responsible Party:** MARATHON OIL COMPANY **Well Operator:** MARATHON OIL COMPANY

Well Name: CLIVE PELTON 34-23H

Field Name: BAILEY Well File #: 17318

Date Incident: 9/18/2015 Time Incident: 08:25 Facility ID Number:

County: DUNN Twp: 146 Rng: 93 Sec: 23 Qtr:

Location Description: A fire tube gasket failed on the Clive Pelton 34-23H causing 33.38 barrels of

fluid to be spilled into secondary containment. The entire spill was contained

within secondary containment.

Submitted By: Duell Petsch Received By:

Contact Person: Duell Petsch

3172 HWY 22 N

DICKINSON, ND 58601

General Land Use: Well/Facility Site Affected Medium: Well/Facility Soil

**Distance Nearest Occupied Building:** 

Distance Nearest Water Well:

Type of Incident: Equipment Failure

Release Contained in Dike: Yes - Within Dike Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units	
Oil	23.2	Barrels	23.2	Barrels	23.16	barrels	
Brine	10.2	Barrels	10.2	Barrels	10.22	barrels	

Other

Description of Other Released Contaminant:

Inspected: Written Report Received: 9/24/2015 Clean Up Concluded: 9/22/2015

#### Risk Evaluation:

Risk evaluation is minimal as nothing got outside the dike, the spill was stopped and cleanup began immediately.

#### Areal Extent:

Entire spill was contained within secondary containment.

## Potential Environmental Impacts:

Environmental impacts are minimal as the entire spill was contained within the dike. The entire spill will be cleaned up and disposed of properly.

## Action Taken or Planned:

The well was shut in to minimize the spill. Once cleanup is complete the gasket will be changed before the well is started back up.

Wastes Disposal Location: Recovered wastes will be disposed of at Clean Harbors.

Agencies Involved:

#### **Updates**

Date: 9/21/2015 Status: Reviewed - Assigned to Other Agency Author: Souder, Taylor

**Updated Oil Volume:** 

**Updated Salt Water Volume:** 

**Updated Other Volume:** 

**Updated Other Contaminant** 

## Notes:

Release, due to equipment failure, remained on location according to the report. NDIC retains oversight.